



Photo 25: Flooded Collapsed Mine Feature at Admiralty Mine Site



Photo 26: Tar Creek at Douthat Bridge (photo taken facing upstream)



Photo 27: Former Lytle Creek at Douthat Bridge (photo taken facing upstream)



Photo 28: Chat in Tar Creek at Douthat Bridge (photo taken facing upstream)



Photo 29: Tar Creek at Douthat Bridge (photo taken facing downstream)



Photo 30: Powerhouse Well in January 2015 (well plugged in February 2015)



Photo 31: Tar Creek at Stateline Road between Oklahoma and Kansas



Photo 32: OU2 Repository Formerly Owned by Picher Development Authority; Property Currently Owned by Quapaw Tribe



Photo 33: OU2 Repository Formerly Owned by Picher Development Authority; Property Currently Owned by Quapaw Tribe



Photo 34: MW-1 at Sooner Pile, Location of Chat Injection Pilot Study




Photo 35: Chat Washing Operation at Sooner Pile



Photo 36: Tulsa Mine Well at Atlas Chat Pile
(well was plugged in February 2015)



Photo 37: Distal 8 Remediation (Catholic 40)



Photo 38: Soil Amendments Placed on Catholic 40 Site



Photo 39: Chat Hauling from Distal 6A



Photo 40: Excavation of Chat from Distal 6A



Photo 41: Catholic 40 Remediation



Photo 42: Soil Amendment Placement on Catholic 40



Photo 43: Distal 6 (CP104) Final Remediation



Photo 44: Distal 7 North; Vegetation Has Yet to Become Established



Photo 45: Distal 1 Final Remediation



Photo 46: "605" Hole



Photo 47: County Subsidence Near 605 Road



Photo 48: Hockerville Subsidence; Settling and Vandalism Present



Photo 49: Hockerville Subsidence; Settling and Vandalism Present



Photo 50: Overview of Picher from Sample Pile



Photo 51: Alleyway Adjacent to Washington Elementary School;
No Chat Present



Photo 52: Limestone Alleyway Adjacent to Washington Elementary School



Photo 53: High-access Area, Limestone Church Parking Lot



Photo 54: Driveway Replacement Near Washington Elementary School



Photo 55: Alleyway Near Roosevelt Elementary School



Photo 56: Driveway Near Roosevelt Elementary School



Photo 57: Alleyway Near Roosevelt Elementary School



Photo 58: Alleyway Near Roosevelt Elementary School



Photo 59: Armory Near Riverview Park; Chat Parking Lot has been Replaced with Limestone



Photo 60: Driveway Replacement at 504 5th NE Road



Photo 61: Yard Replacement in Commerce Under OU2



Photo 62: Yard Replacement in Commerce Under OU2



Photo 63: Yard Replacement in Commerce Under OU2



Photo 64: Yard Replacement in Commerce Under OU2



Photo 65: Yard Replacement in Commerce Under OU2



Figure 1. A typical example of a textured surface.