# Navajo Abandoned Uranium Mine Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits and pits. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites lands not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands but that are or may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, to record all immediate site information associated with the mine site and to document the recommendation and/or decision on what additional steps, if any, are needed at the site.

CD&S AUM site

Navajo AUM Eastern Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.496.1111

May 2009

# Part I **Site Identification, Location and Status** Site Names and ID numbers as applicable Mine ID: 310 Map ID: E18 **CERCLIS:** NNN 000 908 701 NAMLRP: **NOT ASSIGNED** New Mexico Mining and Mineral Division ID: NM0142 New Mexico Bureau of Geology and Mineral Resources: NMMK0028 Local name / Aliases: CDS, Section 35 Chapter and local area: Church Rock Chapter **Lat/Long:** 35.5724835859 N / -108.607095066 W **Nearby road and highway:** NM-371, Interstate 40 Local Post Office: Crownpoint, NM Land Status: check one or more and provide ownership and contact information below **Tribal Trust Land Tribal Fee Land** Allotment Fee land **Public lands Private Bureau of Land Mgmt** State

#### Ownership and contact information:

No ownership was identified. The mine site property is classified as Navajo Tribal Trust land.

#### Part II Site Observations

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

**0 to 200 feet:** None **200 feet to 0.25 mile:** 

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

**0 to 200 feet:** None **200 feet to 0.25 mile:** None

Levels measured around the perimeter(s) of the identified structure(s):

- 4 houses and 2 wells approximately 0.25 miles southeast of site – measured at 9,272 counts per minute (cpm).

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

**0 to 0.25 miles:** None **0.25 miles to 4 miles:** 2 water wells were observed within

the housing complex approximately 0.25 miles east of the site. Field personnel were unable to obtain any information

regarding the usage or origin of the wells (Photo 6).

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None observed

Known Site History: include information from interviews with Chapter officials and residents.

Note information on mine ownership, period of operation, and type of mining operation.

C D and S mine consists of an area of 21,258.22 square meters. Any historical information pertaining to mining operations and historical ownership of the mine site appeared to be unclear.

#### Part III Type, number and reclamation status of mine features

Provide description and reclamation status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all reclamation caps.

Reclamation status of the mine site is currently unknown. No visible signs of reclamation were observed. No waste piles, adits, or other mine features were observed during the site visit. The site was found alongside a large cliff-face, making much of the site inaccessible.

#### Part IV Summary of radiological readings

#### **Background Locations**

#1 9,272 cpm #2 8,410 cpm #3 7,815 cpm

Mine site: C D and S

- See Figures 1 and 2

**Nearby Structure Perimeter** – None

#### **Describe any other radiological measurements:**

A total of 951 gamma radiation measurements were collected from mine sites, ranging from 7,198 cpm to 14,948 cpm. The measurements are represented in Figures 1 and 2.

Part V Site sketch of all mine features and readings, including locations of all structures, sources of drinking water and any other important features and radiological readings.

Presented in Figures 1 and 2

#### Part VI Response Action Summary

**Site Name(s):** C D and S **Chapter:** Church Rock

#### **Decision Criteria**

Is there an unreclaimed waste pile at the site? No

At what distance from the waste pile is the nearest residential structure located? N/A

At what distances from the waste pile are there potential drinking water sources? N/A

Is there a reclamation cap or sealed adit in place at the site? No

Is the cap/seal functionally intact? N/A

Is the cap/seal sufficiently degraded to create a concern about releases? N/A

At what distance from the cap/seal is the nearest domestic structure located? N/A

At what distance from the cap/seal is the nearest domestic drinking water source? N/A

#### **Summary of emergency response factors**

None

#### **Summary hazard ranking system factors**

5 residential houses and 2 water wells were located approximately 0.25 miles from the site. Gamma reading at the site did not exceed two-times background, and readings collected at the houses/wells were found to be consistent with the background levels.

#### **Summary of reclamation factors**

No known reclamation

### Part VII Photos



Photo 1. C D & S mine site, towards the south



Photo 2. C D & S mine site, towards the east



Photo 3. C D & S mine site, towards the southeast



Photo 4. C D & S mine site, towards the southwest



Photo 5. C D & S mine site, towards the northeast

## **Part VIII** Contacts Reports and Information

Name_Stanley Edison
Title or official role (if any) Navajo EPA Superfund Program
AddressPO Box 2946, Window Rock, AZ 86515
Telephone number (928) 871-6861
Information provided <u>General Background and Contact/Access Information</u>
Name
Title or official role (if any)
Telephone number
Information provided
Name
Title or official role (if any)
Telephone number
Information provided
Name
Title or official role (if any)
Telephone number
Information provided



