




Legend

- Existing Monitoring Well (Installed by Others)
- Existing Monitoring Well (Installed by Antea Group (former Delta Consultants))
- Existing Monitoring Well (Installed by Antea Group (former Delta Consultants in 2009))
- (91.53) Groundwater Elevation
- Groundwater Elevation Contour
- ← Generalized Groundwater Flow Direction

All Elevations Shown in Feet
 Contour Interval = 0.50 foot
 ** Anomalous Elevation Not Used in Contouring

0 50 100 200
 Scale 1 inch = 100 feet

GROUNDWATER ELEVATION CONTOUR MAP JUNE 6, 2017			DESIGNED: JMM
FORMER MCCANDLESS FUELS SITE			DETAILED: SGH
2231 Delsea Drive Franklinville, New Jersey		10 LIPPINCOTT LA. MT. HOLLY, NJ 08060 Tel.(856) 273-1009 Fax.(856) 273-1012 1-866-Remedi-8	CHECKED: JMM
SOURCE: anteagroup 20161101_MCCANDLESS.DWG	FILE NAME: 18016_Fig17A	JOB NO.: 18016	DATE: 11/3/2017
			FIGURE: 15A



Legend


- Existing Monitoring Well (Installed by Others)
- Existing Monitoring Well (Installed by Antea Group (former Delta Consultants))
- Existing Monitoring Well (Installed by Antea Group (former Delta Consultants in 2009))

MW-12	SAMPLE ID
6/7/17	DATE
1.83	TOTAL PCBs

Results reported in µg/L (Micrograms per liter).

PCBs Polychlorinated biphenyls.
 ND Not Detected.
 J Result is less than the RL but greater than or equal to the MDL and the concentration is an approximate value.

Bold value exceeds NJDEP Groundwater Quality Standards.
 No exceedances are reported for this sampling event.



POST-OZONE INJECTION
 GROUNDWATER SAMPLING RESULTS
 POLYCHLORINATED BIPHENYLS (PCBs)
 JUNE 7-8, 2017
**FORMER MCCANDLESS
 FUELS SITE**
 2231 Delsea Drive
 Franklinville, New Jersey

RCC Resource Control Consultants
 10 LIPPINCOTT LA. MT. HOLLY, NJ 08060
 Tel.(856) 273-1009 Fax.(856) 273-1012
 1-866-Remedi-8

SOURCE: anteagroup
 20161101_MCCANDLESS.DWG

FILE NAME: 18016_Fig17B

DESIGNED: JMM
DETAILED: SGH
CHECKED: JMM
DATE: 11/3/2017
FIGURE: 15B