

**WIPP TOUR AGENDA
EPA and NMED
IVS Coefficient of Variation testing
UG tour including SVS Fan
April 26-27, 2016**

Tuesday, April 26, 2016

- 7:00 a.m. Visitors arrive at WIPP site. Met at the gate by Russ Patterson, Larry Madl and Yen Kiang
 - Security to provide underground safety briefing (visitors have taken GET)
- 7:15 a.m. - Proceed to Training Building, Training Room 4
 - Donning self-rescuers (W65/SCSR) - John Fernandez
- 8:00 a.m. Proceed to Lamp Room for PPE, accountability tags/radios
 - UG Escorts: Vandekraats, Farnsworth, Zimmerly, Boatwright to meet in Lamp Room
- 10:00 a.m. Return to surface
- 10:30 a.m. Observe Station B (RadCon assist, meet when visitors come topside)
- 11:00 a.m. Break for lunch in snack bar (optional)
- 12:00 p.m. Observe Coefficient of Variation testing
- 5:00 p.m. Testing completed. Visitors depart site

Wednesday, April 27, 2016

Agenda to be determined

Photo ID Required

Prohibited attire: dresses, skirts, shorts, open-toe shoes, high-heeled shoes and sandals

Revised: 4/22/2016