



Electro-Plating – 1696 Incident

January 3, 2020 Update



As of January 2, 2020

- Basement Sump
 - Estimate 9,264 gallons collected
- 696-Embankment Sump
 - Estimated 1,345 gallons collected
- Subsurface Investigation
 - 10 Temporary Wells
 - 4 Permanent Wells
- Hydraulic Profiling
 - 11 Temporary Wells

January 3, 2020

- Collect Groundwater Samples from Wells
- Additional Temporary Wells
- Additional HPT Investigation

As of January 2, 2020

- Catch Basin Sampling
 - 3 – I-696
 - 3 – Service Drive
 - Bear Creek













