







's Plant





Plant






ELECTRICAL ROOM


← Wiring destroyed
(this depicts 1 of 3
boxes)

Electrical Fuse Boxes Wiring
Destroyed ↓






Wiring pulled & cut from
Fuse Boxes



Work Machines Destroyed



Hough 90E Series loader
(Guts torn out...)

WORK ROOM DESTRUCTION
Industrial Tools Stolen
(Slag Plant)



Plexiglass - after
(continued)

