




**Figure 1.** Savannah River Basin



**Figure 2.** Sampling Site Locations





**Figure 3. HUC 3060101 Sampling Site Results**




**Figure 4.** HUC 3060102 Sampling Site Results








**Figure 6.** HUC 3060104 Sampling Site Results











**Figure 9.** HUC 3060107 Sampling Site Results





**Figure 10.** HUC 3060108 Sampling Site Results




**Figure 11.** HUC 3060109 Sampling Site Results



**Figure 12.** HUCs and Subbasins



**Figure 13.** Ecoregions of the Savannah River Basin



**Figure 14.** Roads crossing Streams and Dams in Selected Subbasins



# Savannah River

## Sampling Site S68 Drainage





Figure 15. Sampling Site S68 Drainage.

# Savannah River

## Sampling Site S113



**Figure 16.** Sampling Site S113 Drainage

# Savannah River

## Sampling Site S195 Drainage




Figure 17. Sampling Site S195 Drainage

# Savannah River

## Sampling Site S22 Drainage




Figure 18. Sampling Site S22 Drainage



# Savannah River

## Sampling Site S80 Drainage




Figure 19. Sampling Site S80 Drainage



# Savannah River

## Sampling Site S149 Drainage





Figure 20. Sampling Site S149 Drainage




**Figure 21.** Mosaic of circa 1970 NALC images.




**Figure 22.** Mosaic of circa 1992 NALC images.





**Figure 23.** Gains (green) and losses (red) in vegetation, 1970s to 1990s



1970s




1990s

### Savannah River Basin

**Figure 24.** Lake Russell was created between the 1970s and 1990s.





**Figure 25.** Land Surface Loss to Lake Russell in Subbasin #26.