

FIGURE 4-10 TOP OF BEDROCK GROUNDWATER PLUME (TEMPORARY WELLS and PERMANENT WELLS)
 TCE CONTAMINATION, OCTOBER/NOVEMBER 1996
 REMEDIAL INVESTIGATION REPORT
 NORTH BELMONT PCE SUPERFUND SITE
 NORTH BELMONT, GASTON COUNTY, NC
 SESD PROJECT No. 96S-058, JUNE 1997

NOT TO SCALE






FIGURE 4-11 TOP OF BEDROCK GROUNDWATER PLUME (TEMPORARY WELLS and PERMANENT WELLS)
 CIS-1,2 DCE CONTAMINATION, OCTOBER/NOVEMBER 1996
 REMEDIAL INVESTIGATION REPORT
 NORTH BELMONT PCE SUPERFUND SITE
 NORTH BELMONT, GASTON COUNTY, NC
 SESD PROJECT No. 96S-058, JUNE 1997

NOT TO SCALE






FIGURE 4-12 BEDROCK GROUNDWATER PLUME (BEDROCK MW and POTABLE WELLS) NOT TO SCALE
 PCE CONTAMINATION, OCTOBER/NOVEMBER 1996
 REMEDIAL INVESTIGATION REPORT
 NORTH BELMONT PCE SUPERFUND SITE
 NORTH BELMONT, GASTON COUNTY, NC
 SESD PROJECT No. 96S-058, JUNE 1997

DGRIFA12.CDR







FIGURE 4-13 BEDROCK GROUNDWATER PLUME (BEDROCK MW and POTABLE WELLS) TCE CONTAMINATION, OCTOBER/NOVEMBER 1996
 REMEDIAL INVESTIGATION REPORT
 NORTH BELMONT PCE SUPERFUND SITE
 NORTH BELMONT, GASTON COUNTY, NC
 SESD PROJECT No. 96S-058, JUNE 1997


DGRIFA13.CDR






NBL 8415

1000 0 1000 2000 Feet



NBL 1418

1000 0 1000 2000 Feet



MDL 4417

