

RCRA Facility Investigation Report

Corrective Action Order on Consent

Docket No. RCRA-08-2004-0001

Silver Bow Plant

Butte, Montana

Prepared for

Rhodia Inc

May 2013



RCRA Facility Investigation Report

***Corrective Action Order on Consent
Docket No. RCRA-08-2004-0001
Silver Bow Plant
Butte, Montana***

***Prepared for
Rhodia Inc***

May 2013



4700 West 77th Street
Minneapolis, MN 55435-4803
Phone: (952) 832-2600
Fax: (952) 832-2601

**RCRA Facility Investigation Report
Corrective Action Order on Consent
Docket No. RCRA-08-2004-0001
Silver Bow Plant
Butte, Montana**

May 2013

Table of Contents

Volume 1 of 4

1.0	Introduction	1-1
1.1	Purpose and Scope	1-1
1.2	Site Setting, Operations and Current Conditions	1-1
1.3	Previous Investigation Reports	1-3
1.3.1	Previous Investigations	1-3
1.3.2	Other Data Sources	1-9
1.4	Report Organization.....	1-11
1.5	References.....	1-12
2.0	Site Background	2-1
2.1	Facility Operations.....	2-1
2.1.1	Ownership History	2-1
2.1.2	Process Description.....	2-1
2.2	Plant Demolition	2-7
2.2.1	Disposition of Underground Piping	2-8
2.3	Land Use and Surrounding Area.....	2-9
2.3.1	Land Use	2-9
2.3.2	Groundwater Use	2-14
2.4	Regulatory History and Environmental Compliance	2-15
2.4.1	Environmental Permits, Exemptions and Registrations.....	2-15
2.4.2	Compliance History	2-15
2.4.3	Other Regulatory Activity.....	2-17
2.5	Waste Streams, Solid Waste Management Units and Areas of Concern	2-19
2.5.1	Identification of SWMUs and AOCs	2-19
2.5.2	Material/Waste Stream Characteristics.....	2-20
2.5.3	Other Releases	2-28
2.6	References.....	2-2

3.0 Conceptual Site Model	3.0-1
3.1 Geology.....	3.1-1
3.1.1 Regional Geology	3.1-1
3.1.2 Site Geology.....	3.1-3
3.1.3 Graben-Fill Deposits.....	3.1-4
3.1.4 Geophysical Surveys.....	3.1-5
3.1.5 Summary of Site Geology.....	3.1-5
3.1.6 References.....	3.1-6
3.2 Hydrogeology	3.2-1
3.2.1 Site Groundwater Flow Directions	3.2-1
3.2.2 Regional Context	3.2-2
3.2.3 Site Context.....	3.2-6
3.2.4 Conceptual Site Hydrogeologic Model.....	3.2-15
3.2.5 Summary and Data Gaps	3.2-16
3.2.4 References.....	3.2-18
3.3 Hydrology	3.3-1
3.3.1 Surface Water Flow Investigation.....	3.3-1
3.3.2 Silver Bow Creek Hydrology.....	3.3-3
3.3.3 Beaver Pond Hydrology.....	3.3-6
3.3.4 Sheep Gulch Hydrology.....	3.3-7
3.3.5 Hydrogology Summary.....	3.3-8
3.3.6 References.....	3.3.9
4.0 Background/Reference Area Evaluation	4-1
4.0.1 References.....	4-2
4.1 Upstream Surface Water Quality	4.1-1
4.1.1 Sheep Gulch.....	4.1-1
4.1.2 Silver Bow Creek.....	4.1-3
4.1.3 Conclusions and Recommendations	4.1-5
4.1.4 References.....	4.1-5
4.2 Upstream Sediment Quality	4.2-1
4.2.1 Sheep Gulch.....	4.2-1
4.2.2 Conclusions and Recommendations	4.2-3
4.2.3 References.....	4.2-4
4.3 Upgradient Groundwater Quality.....	4.3-1
4.3.1 Regional Background Groundwater Quality.....	4.3-1
4.3.2 Site Upgradient Background Groundwater Quality.....	4.3-3

4.3.3	Possible Upstream Elevated or Anomalous Constituent Sources	4.3-15
4.3.4	Conclusions.....	4.3-17
4.3.5	References.....	4.3-18
4.4	Background/Reference Area Soil.....	4.4-1
4.4.1	Soil Background/Reference Area Investigation – SSTOU	4.4-1
4.4.2	Soil Background/Reference Area Investigations – Silver Bow Plant.....	4.4-2
4.4.3	Background/Reference Area Soil Quality Data	4.4-4
4.4.4	Statistical Analysis.....	4.4-8
4.4.5	Comparison to Montana DEQ Background Soil Concentrations	4.4-9
4.4.6	Conclusions.....	4.4-9
4.4.7	References.....	4.4-10

Volume 2 of 4

5.0 Investigation Activities and Results

5.1	Surface Water.....	5.1-1
5.1.1	Surface Water Investigations Prior to RFI.....	5.1-1
5.1.2	RFI Surface Water Quality Investigation.....	5.1-1
5.1.3	Surface Water Quality Results.....	5.1-2
5.1.4	References.....	5.1-25
5.2	Sediment	5-2-1
5.2.1	Sediment Investigations Prior to RFI.....	5.2-1
5.2.2	2008 Sediment Investigation.....	5.2-1
5.2.3	2012 Sediment Investigation.....	5.2-2
5.2.4	Sediment Investigation Results.....	5.2-3
5.2.5	Cumulative Sediment Quality Summary	5-2-16
5.2.6	Conclusions.....	5.2-18
5.2.7	References.....	5.2-18
5.3	Groundwater	5.3-1
5.3.1	Groundwater Quality Investigation Activities	5.3-1
5.3.2	Groundwater Quality Investigation Results	5.3-4
5.3.3	Conclusions.....	5.3-34
5.3.4	References.....	5.3-37

Volume 3 of 4

5.4	Site-Wide Native Soil	5.4-1
5.4.1	Native Soil Quality Investigation.....	5.4-1
5.4.2	XRF Evaluation	5.4-14
5.4.3	References.....	5.4-18
5.5	Solid Waste Management Units and Areas of Concern	
5.5.1	SWMU 1 – Tailing Basin and Water Recirculation System.....	5.5.1-1
5.5.2	SWMU 2 – Clarifier.....	5.5.2-1
5.5.3	SWMU 3 – Used Carbon Brick and Furnace Liner Pile	5.5.3-1
5.5.4	SWMU 4 – Used Carbon Blocks, Floor Logs and Furnace Liner Pile	5.5.4-1
5.5.5	SWMU 5 – New and Used Carbon Block and New Carbon Brick.....	5.5.5-1
5.5.6	SWMU 6 – Raw Materials Area	5.5.6-1

Volume 4 of 4

5.5.7	SWMU 7 – Elemental Phosphorus Production Area	5.5.7-1
5.5.8	SWMU 8 – Used Pump Area.....	5.5.8-1
5.5.9	SWMU 9 – Coke Fines Area	5.5.9-1
5.5.10	SWMU 10 – Coal Stockpile Area.....	5.5.10-1
5.5.11	SWMU 11 – Crude Phosphorus Burial Area	5.5.11-1
5.5.12	SWMU 12 – Coarse Slag Pile.....	5.5.12-1
5.5.13	SWMU 13 – Granulated Slag Pile	5.5.13-1
5.5.14	SWMU 14 – Roaster Solids Area	5.5.14-1
5.5.15	SWMU 15 – Precipitator Dust Burial Area	5.5.15-1
5.5.16	SWMU 16 – Buried Precipitator Dust Pans Area.....	5.5.16-1
5.5.17	SWMU 17 – Removed Precipitator Dust Pans Area	5.5.17-1
5.5.18	SWMU 18 – Scrap Steel and Scrap Tin Bales Areas.....	5.5.18-1
5.5.19	SWMU 19 – Refuse Disposal Area	5.5.19-1
5.5.20	SWMU 20 – Scrap Steel and Equipment Burial Area	5.5.20-1
5.5.21	SWMU 21 – Former Transformer Storage Area.....	5.5.21-1
5.5.22	SWMU 22 – Slag Granulation Water and Temporary Retention Ditch	5.5.22-1
5.5.23	SWMU 23 – Septic Tanks and Septic Drain Field	5.5.23-1
5.5.24	SWMU 24 – Discharge Pipe Area	5.5.24-1
5.5.25	SWMU 25 – Containment Pad Area.....	5.5.25-1
5.5.26	SWMU 26 – Ferrophosphorus Area	5.5.26-1

5.5.27 SWMU 27 – Final Pump Station	5.5.27-1
5.5.28 AOC A – Petroleum Storage Areas	5.5.28-1
5.5.29 AOC B – Sulfuric Acid Tank.....	5.5.29-1
6.0 Recommendations	6-1
6.1 Surface Water.....	6-1
6.2 Sediment	6-1
6.3 Groundwater	6-2
6.4 Soil - Natural and Undeveloped Areas	6-2
6.5 SWMUs and AOCs.....	6-2
6.6 References.....	6-2