






ATTACHMENT 25


RADIO MATERIALS CORPORATION

FIGURE — SIMULATED HYDRAULIC CONTAINMENT FOR GROUNDWATER INTERIM CORRECTIVE
MEASURES



ATTACHMENT 26
RADIO MATERIALS CORPORATION
FIGURES – PCE AND TCE CONCENTRATIONS IN OVERBURDEN GROUNDWATER FROM FEBRUARY 2014
AND NOVEMBER 2014







ATTACHMENT 27

RADIO MATERIALS CORPORATION

FIGURES – SUMMARY OF VOC DETECTIONS ABOVE THE RDCLs IN THE OVERBURDEN AQUIFER
(SEPTEMBER 2008 – JULY 2009) AND SUMMARY OF 2014 SEMIANNUAL GROUNDWATER ANALYTICAL
RESULTS FOR SELECTED CVOCS





RADIO MATERIALS CORPORATION
ATTICA, INDIANA

SUMMARY OF 2014 SEMIANNUAL GROUNDWATER ANALYTICAL RESULTS FOR SELECTED CUDOS

CONESTOGA-ROVERS & ASSOCIATES

Project: 19156-21
Date: 11/16/21
Page: 1 of 1

SCALE VERIFICATION

THIS MAP WAS MADE FROM AERIAL PHOTOGRAPHS.

LEGEND

- Radio Tower
- Service Area
- Water Body
- Highway
- Other

DATA TABLE

Tower ID	Frequency	Power	Height	Location
1001	157.040 MHz	100 Watts	100 feet	1001
1002	157.040 MHz	100 Watts	100 feet	1002
1003	157.040 MHz	100 Watts	100 feet	1003

ATTACHMENT 28
RADIO MATERIALS CORPORATION
FIGURE – 2014 AND 2015 SOIL VAPOR RESULTS

