

ATTACHMENT 4  
RADIO MATERIALS CORPORATION  
FOUNTAIN WARREN COUNTY HEALTH DEPARTMENT INSPECTION PHOTOS – AUGUST 21, 2015





Photo 1	9:54 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 1.	



Photo 2	9:54 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
---------	--

Building 1.
-------------





Photo 3	9:54 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 1.	



Photo 4	10:03 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 1.	



Photo 5	10:05 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Between Buildings 1 and 2.	





Photo 6	10:05 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	



Photo 7	10:06 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
---------	---

Building 2.
-------------





Photo 8	10:07 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	



Photo 9	10:08 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
---------	---

Building 2.
-------------





Photo 10	10:08 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
----------	---

Building 2.



Photo 11	10:10 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	



Photo 12	10:10 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	





Photo 13	10:10 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	



Photo 14 10:10 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana

Building 2.





<b>Photo 15</b>	10:10 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	




Photo 16	10:11 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	



Photo 17	10:12 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	





Photo 18	10:12 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
----------	---

Building 2.
-------------




Photo 19	10:12 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	




Photo 20	10:12 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	






Photo 21	10:13 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2. Chemical storage.	




Photo 22	10:14 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2. Chemical storage.	






Photo 23	10:14 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2. Chemical storage.	




Photo 24	10:15 am EDT
	August 21, 2015
	Radio Materials Corporation, Attica, Indiana
Building 2. Chemical storage.	



Photo 25	10:15 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2. Chemical storage.	






Photo 26	10:18 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 3.	



Photo 27 10:19 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana  
Building 3.





Photo 28	10:19 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 3.	





Photo 29	10:19 am EDT
	August 21, 2015
Radio Materials Corporation, Attica, Indiana	
Building 3.	




Photo 30	10:20 am EDT
	August 21, 2015
Radio Materials Corporation, Attica, Indiana	
Building 3.	




Photo 31 10:21 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana  
Building 3.






Photo 32	10:22 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
	Building 3.



Photo 33	10:22 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 3.	



Photo 34	10:24 am EDT
	August 21, 2015
	Radio Materials Corporation, Attica, Indiana
Building 3.	






Photo 35 10:25 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana  
Building 3.




Photo 36 10:25 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana  
Building 3.



Photo 37	10:26 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 3.	





Photo 38	10:26 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 3.	



Photo 39	10:27 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Between Buildings 2 and 3.	



Photo 40	10:27 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	






Photo 41	10:28 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	



Photo 42	10:28 am EDT
	August 21, 2015
Radio Materials Corporation, Attica, Indiana	
Building 4.	



Photo 43	10:31 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	





Photo 44	10:32 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
----------	---

Building 4.
-------------



Photo 45	10:33 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
	Building 4.



Photo 46	10:33 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
----------	---

Building 4.
-------------






Photo 47	10:34 am EDT
	August 21, 2015
Radio Materials Corporation, Attica, Indiana	
Building 4.	



Photo 48	10:34 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	



Photo 49 10:34 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana  
Building 4.





Photo 50 10:34 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana  
Building 4.



Photo 51	10:35 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	





Photo 52 10:35 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana

Building 4.






Photo 53 10:35 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana  
Building 4.




Photo 54	10:35 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	

Radio Materials Corporation  
August 21, 2015 Site Photos  
Fountain Warren County Health Department  
Photos by Environmental Health Specialists Greg F. Robison and Erich Haley  
Attachment 4 to EPA Focused Compliance Investigation Report




Photo 55	10:35 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	






Photo 56 10:36 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana  
Building 4.




Photo 57 10:36 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana  
Building 4.




Photo 58	10:37 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	






Photo 59	10:37 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	



<b>Photo 60</b>	10:37 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	





Photo 61	10:37 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	





<b>Photo 62</b>	10:38 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	




Photo 63 10:39 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana  
Building 4.



Photo 64	10:39 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	





Photo 65	10:39 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	




Photo 66	10:39 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	




Photo 67	10:39 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	





Photo 68	10:42 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4B.	



Photo 69	10:42 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4B.	






Photo 70	10:43 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4B.	





Photo 71	10:43 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4B.	



Photo 72	10:44 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
----------	---

Building 4B.
--------------



Photo 73	10:45 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4B.	





Photo 74	10:47 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
----------	---

Building 4B.




Photo 75 10:48 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana

Building 4B.





Photo 76	10:48 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Outside Quality Control Room.	





<b>Photo 77</b>	10:48 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Outside Quality Control Room.	



Photo 78	10:49 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Outside Quality Control Room.	





Photo 79	10:49 am EDT
	August 21, 2015
Radio Materials Corporation, Attica, Indiana	
Outside Quality Control Room.	





Photo 80	10:48 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana Outside Quality Control Room.
----------	--



Photo 81	10:50 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Quality Control Room.	




Photo 82	10:50 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Quality Control Room.	






Photo 83 10:50 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana  
Quality Control Room.



Photo 84 10:54 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana  
Quality Control Room.






Photo 85    10:54 am EDT  
 August 21, 2015  
 Radio Materials Corporation, Attica, Indiana  
 Quality Control Room.





Photo 86 10:57 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana  
Quality Control Room.



Photo 87	10:58 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	



Photo 88	10:58 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
----------	---

Building 2.
-------------





Photo 89 11:05 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana

Building 5.




Photo 90	11:05 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
	Building 5.





Photo 91 11:05 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana

Building 5.





Photo 92	11:06 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	




Photo 93	11:06 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	



Photo 94	11:06 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
----------	---

Building 5.





Photo 95	11:07 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	



Photo 96	11:08 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	



Photo 97	11:08 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	






Photo 98	11:09 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	



Photo 99 11:13 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana





Photo 100	11:14 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	





Photo 101	11:14 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	



Photo 102	11:14 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	





Photo 103	11:14 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	





Photo 104	11:15 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	




Photo 105	11:19 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	





Photo 106	11:20 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	






Photo 107	11:21 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	



Photo 108	11:21 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	





Photo 109	11:22 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	





Photo 110	11:22 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	



Photo  
111

11:25 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana

Building 5.





Photo 112	11:25 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	






Photo 113	11:33 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	




Photo 114	11:51 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	



Photo 115	11:51 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	





Photo 116	11:51 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	



Photo 117	11:51 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	



Photo 118	11:52 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	





Photo 119	11:52 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	



Photo 120	11:52 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	



Photo 121	11:52 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	





Photo  
122

11:52 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana

Building 8.



Photo 123	11:53 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	



Photo 124	11:53 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	





Photo  
125

11:54 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana

Building 8.




Photo 126	11:54 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	



Photo 127	11:55 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	





Photo 128	11:55 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	



Photo 129	11:56 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	





Photo 130	11:56 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	






Photo  
131

11:56 am EDT  
August 21, 2015  
Radio Materials Corporation, Attica, Indiana

Building 8.



Photo 132	12:00 pm EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Recovery system outside Buildings 6-7.	





Photo 133	12:00 pm EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Recovery system outside Buildings 6-7.	





Photo 134	12:01 pm EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Recovery system outside Buildings 6-7.	



Photo 135	12:01 pm EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Recovery system outside Buildings 6-7.	





Photo 136	12:02 pm EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana Recovery system outside Buildings 6-7.
--------------	---





Photo 137	12:02 pm EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Recovery system outside Buildings 6-7.	

