



June 10, 2008

Mr. Scott Ferguson Wisconsin Department of Natural Resources 2300 North Dr. Martin Luther King Drive Milwaukee, WI 53212

Subject:

Twelfth Semi-Annual Progress Report Interim Measure Implementation

PPG Industries, Inc. Oak Creek, Wisconsin Facility

Dear Mr. Ferguson:

This letter is being submitted to fulfill the progress reporting requirements under Wisconsin Administrative Code (WAC) NR 700 at the PPG Industries, Inc. site located at 10800 South 13th Street in Oak Creek, Wisconsin. This report describes continuing activities undertaken by PPG to address a spill of xylene and naphtha initially reported to the Wisconsin Department of Natural Resources (WDNR) on February 12, 2002. Additionally, this letter presents the anticipated activities that will occur during the next six months.

Activities Undertaken Since November 2007

Environmental contractor Tetra Tech continues to assist in the monitoring and remediation activities. PPG has continued to pump groundwater from well MW-1 in order to maintain containment in the vicinity of the release. The water is pumped through a two-stage carbon filtration system from a level-activated pump in well MW-1. Water passing through the carbon filter is discharged to the POTW in accordance with the facility's sewer discharge permit. The volume of water pumped varies depending on precipitation recharge but has averaged approximately 200 gallons per day.

On May 28, 2008, the monitoring wells were checked for light nonaqueous phase liquid (LNAPL); water levels were measured and groundwater samples were collected. On this occasion, LNAPL was not present in any of the wells. Note that MW-1 had the pump installed, but no free product was observed. Samples were collected from monitoring wells MW-1, MW-2, MW-3, MW-4, MW-5 and MW-6. The sample collected from MW-1 was collected by threading a 0.5" bailer past the dedicated pumping equipment and then lowering the bailer into the water column.

The analytical data showed a significant decrease in both ethylbenzene and xylene at wells MW-1, MW-2 and MW-3 compared to the concentrations observed in November 2007 and historically since November 2003. The concentrations in wells MW-5 and MW-6 were all non-detect for both ethylbenzene and xylene. The analytical results at MW-5 have been non-detect for the tenth consecutive sampling event. Ethybenzene concentrations in MW-4 have also been historically non-detect, however, xylene was detected in this well at a concentration below the laboratory reporting limit. No constituents were detected above their respective Enforcement Standard and only xylene exceeded the Preventive Action Level in monitoring wells MW-2 and MW-3. The following table provides a summary of the May 2008 sampling results from the Site wells; Table 1 provides a summary of the results of all of the sampling events.

		Ethylbenzene	Xylenes		
	Preventive Action Level:	140	1,000 10,000		
- W 1/4	Enforcement Standard:	700			
Well Number	Date				
MW-1	5/28/08	26.5	97.6 1,045		
MW-2	5/28/08	105			
MW-3	5/28/08	332	2,868		
MW-4	5/28/08	<0.4 (1)	1.70 J <1.1		
MW-5	5/28/08	<0.4			
MW-6	5/28/08	<0.4	<1.1		

Notes:

All concentrations in µg/l.

"J" indicates estimated concentration below laboratory quantitation level.

(1) "<" indicates less than reporting limit.

Planned Activities

PPG will continue to pump groundwater through the existing treatment system until treatment is no longer required to comply with permit discharge limitations. Groundwater sampling will continue on a semiannual basis and the wells will be checked for the presence of LNAPL. Water quality samples from monitoring wells MW-1 through MW-6 will be evaluated relative to WAC groundwater quality standards and alternative treatment options will be evaluated if results indicate a significant increase in concentrations. The next sampling event is scheduled for November 2008.

Closing

PPG will submit semi-annual progress reports to WDNR and advise immediately if there is any significant change in conditions at the site. If you have any questions regarding this submittal, or require any further information, please contact me at (414) 764-6000 x374.

Sincerely,

Tom Tersine.

Manager, Environmental Health & Safety

cc:

Jason Chapelle - WDNR S.E. Region, Water Division

Brian McGuire – PPG EHS, Allison Park

Jason Trentini - Tetra Tech NUS, Inc.

TABLE 1 Summary of Historical Groundwater Sample Results PPG Inc., Oak Creek, Wisconsin Facility

	MW-1		MW-2		MW-3		MW-4		MW-5		MW-6	
Date	Ethylbenzene	Xylene	Ethylbenzene	Xylene	Ethylbenzene	Xylene	Ethylbenzene	Xylene	Ethylbenzene	Xylene	Ethylbenzene	Xylene
6/21/02	N/S ⁽¹⁾	N/S	N/S	N/S	N/S	N/S	N/S	N/S	510	2,550	0.28	1.05
3/4/03	N/S	N/S	N/S	N/S	N/S	N/S	1,100	9,200	230	677.4	< 0.53	<1.83
11/04/03	940	10,600	N/S	N/S	N/S	N/S	N/S	N/S	< 0.54(2)	<2.63	< 0.54	<2.63
4/29/04	N/S	N/S	10,000	89,000	6,000	49,000	1.9	72	< 0.54	<2.63	< 0.54	<2.63
11/03/04	1,400	12,200	3,900	47,000	3,500	39,000	4.6	310	< 0.54	<2.63	< 0.54	<2.63
05/04/05	400	2,000	11,000	99,000	10,000	81,000	< 0.54	<2.63	< 0.54	<2.63	<0.54	<2.63
12/22/05	480	3,420	15,000	123,000	11,000	97,000	< 0.54	<2.63	<0.54	<2.63	< 0.54	<2.63
5/30/06	310	2,460	6,600	61,000	2,000	18,700	<0.54	<2.63	< 0.54	<2.63	<0.54	<2.63
11/09/06	430	1,520	14,000	110,000	12,000	99,000	<0.4	<1.1	<0.4	<1.1	<0.4	<1.1
05/10/07	1,400	7,800	11,000	82,000	8,800	71,000	<1.1	<5.3	<0.54	<2.63	< 0.54	<2.63
11/20/07	1,200	6,550	47,100	371,000	14,800	112,900	< 0.50	1.04 J	< 0.50	<0.62	<0.50	1.23 J
5/28/08	26.5	97.6	105	1,045	332	2,868	<0.4	1.70 J	<0.4	<1.1	<0.4	<1.1

Notes:

All concentrations in μg/l.


⁽¹⁾ N/S indicates not sampled.
(2) "<" indicates less than reporting limit.

CERTIFIED MAIL.



PPG Industries Coatings and I

PPG Industrie: Coatings and I 10800 South 1. Oak Creek, Wis



7007 3020 0002 4316 8045
RETURN SERVICE REQUESTED



TETRA TECH NUS, Inc.,
Mr. JASON TRENTINI
ROAM NORTH SHORE CENTRE
600 RIVER AVENUE Suite 203
Pittsburgh, PA 15212