

Table 5
 US EPA Split Sample Results
 Former McCandless Fuels
 2231 Delsea Drive
 Franklinville, New Jersey

	Sample Elevation	Sample Depth (ft bgs)	Depth Interval	Test America Result	EPA Result	Test America Result	EPA Result	Test America Result	EPA Result	Test America Result	EPA Result
Event No.				0	0	2	2	4	4	6	6
Location				10/7/2010	9/20/2010	9/8/2011	9/8/2011	9/1/2012	8/30/2012	9/13/2013	9/12/2013
PMP-22	97.25	1.75	Vadose	5.3	0.6J	12	3	0.05		0.32	0.42
PMP-23	97.25	1.75	Vadose	74	2.0DJ	1	2.2	80	113.1	0.18	0.14
PMP-24	93.75	5.25	Deep Vadose	9800		5400	6031.2	7800	8377.7	890	
PMP-24	91.75	7.25	Water Table	8000		5700		1900		1300	
PMP-24	88.75	10.25	Saturated	480	721	830	947.3	1700	7821.4	100	695.1

units: mg/kg
 J = Estimated Value